




Safety Grooving & Grinding

Midwest Division
Southeast Division

I-10 Escambia Bay Bridge Replacement



Owner:
Florida DOT



Damage by Hurricane Ivan, 2004

Pensacola, FL

Phase I completed in 2006

79,315 SY Bridge Deck Grooving (SGG-SE)

52,669 SY Diamond Grinding (SGG-MW)

Phase II, Summer 2007

Prime: Tidewater-Skanska/Flatiron Constructors, JV

